FIELD OBSERVATION REPORT PERMIT # BLDC-00620-2022

		7	
		Report No. 54	Page 1 of 2
Project:	Oceans West One Condominium	Inspection For:	Building Repair and WP Project
Day/Date:	Thursday, January 26, 2023	Job No.	20-1153
Location:	1 Oceans West Blvd. DBS, FL 32118	Engineer:	Christopher B. Longman, P.E.
Contractor:	SPEC Contractor Services	Project Foreman:	
Subcontractor:	None	Inspector:	Christopher Longman P.E
Weather:	66 Degrees @ 1:00 P.M. Sunny	Calm win	
Workforce Total:	16		
Activities:	Tower A: 04/05 stack punch-out, 05/06 sta staging	ick stucco, 01/02 sta	ack concrete repair, 02/03 stack

Observation Report:

<u>Tower A</u>: Contractor requested an inspection for the installation of a new post tensioned cable anchor and reinforcing steel at the balcony slab edge of Unit 7A6 (05/06 stack). The cable was previously identified within a slab repair and the anchor was not present. A new anchor was installed with new backing reinforcement. The Contractor was directed to install a pocket former before casting the repair. The repair was approved to be cast back.

All stucco is re-applied at the 05/06 balcony stack and the Contractor will prepare to start painting. The deck coating process is complete at the 04/05 balcony stack and punch-out work is in-progress. Concrete repairs are in-progress at the 01/02 balcony stack. Staging is in the process of being installed at the 02/03 balcony stack.

<u>Garage</u>: Post tensioned cable repairs remain in-progress in the parking garage. The Contractor moved to the banded set just North of the electrical room. Removal of a broken cable is in-progress.

UNITED ENGINEERING CONSULTANTS

Christopher B. Longman, P.E. Florida License No. 82452

ONAL ENGINEERS

Christopher B. Longman, PE


82452

Digitally signed by Christopher B. Longman, PE 82452

Date: 2023.01.31 07:37:49

-05'00'

This item has been electronically signed and sealed by Christopher B. Longman using a digital signature and date. Printed copies of this document are not considered signed and sealed and the SHA authentication code must be verified on any electronic copies.



Photograph #1: Post tensioned cable anchor installed



Photograph #2: Concrete repair in-progress at the 01/02 balcony stack